

HARTBEARBEITUNG

ÜBERSICHT TORUS-, VOLLRADIUS UND SCHAFTFRÄSER BIS 54 HRC, 63 HRC UND 67 HRC

	SCHAFTFRÄSER	TORUS	VOLLRADIUS	KOLLISIONS-SCHUTZ	KONISCHE AUSFÜHRUNG	KURZ	LANG	MICRO GENAU	Z 2	Z 4	Z 6+	BIS 54 HRC	BIS 63 HRC	BIS 67 HRC
WZF 122481	●	●		●		●				●		●		
WZF 17416		●		●		●			●			●		
WZF 17418		●		●		●				●		●		
WZF 17426		●		●			●		●			●		
WZF 17428		●		●			●			●		●		
WZF 17436		●		●	●		●		●			●		
WZF 17446		●		●	●		●		●			●		
WZF 17476		●				●			●			●		
WZF 18416			●	●		●			●			●		
WZF 18426			●	●			●		●			●		
WZF 18418			●	●		●				●		●		
WZF 18428			●	●			●			●		●		
WZF 18436			●	●	●		●		●			●		
WZF 18446			●	●	●		●		●			●		
WZF 18466			●			●			●			●		
WZF 18476			●				●		●			●		
	SCHAFTFRÄSER	TORUS	VOLLRADIUS	KOLLISIONS-SCHUTZ	KONISCHE AUSFÜHRUNG	KURZ	LANG	MICRO GENAU	Z 2	Z 4	Z 6+	BIS 54 HRC	BIS 63 HRC	BIS 67 HRC
WZF 125487	●			●		●				●			●	
WZF 13546	●					●					●		●	
WZF 13556	●						●				●		●	
WZF 135461	●	●		●		●					●		●	
WZF 13576	●			●			●				●		●	
WZF 17576		●		●		●				●			●	
WZF 17586		●		●			●			●			●	
WZF 18516			●	●		●			●				●	
WZF 18518			●	●		●				●			●	
WZF 18526			●	●			●		●				●	
WZF 18528			●	●			●			●			●	
WZF 27596		●		●		●	●	●	●				●	
WZF 28596			●	●		●	●	●	●				●	
	SCHAFTFRÄSER	TORUS	VOLLRADIUS	KOLLISIONS-SCHUTZ	KONISCHE AUSFÜHRUNG	KURZ	LANG	MICRO GENAU	Z 2	Z 4	Z 6+	BIS 54 HRC	BIS 63 HRC	BIS 67 HRC
WZF 13746	●			●		●		●		●	●			●
WZF 137461	●			●		●		●		●	●			●
WZF 137463	●			●		●		●		●	●			●
WZF 13756	●			●			●	●		●	●			●
WZF 27796		●		●		●	●	●	●					●
WZF 27798		●		●		●	●	●		●				●
WZF 28796			●	●		●	●	●	●					●
WZF 28798			●	●		●	●	●		●				●

